## CUSTOMER:
JSC “Malkų įlankos terminalas”




## PROJECT:
Cleaning the inside of silo tanks

## WHERE:
Klaipeda, Lithuania

## INVOLVED PERSONNEL:
Rope access technicians

## PERIOD:
2014

## SCOPE OF WORKS:
- One tank was wshed with water under high pressure.
- The second tank was purified by dry method.

Works were carried out without the use of expensive scaffolding.









