CV

UAB KLAIPĖDOS NK CENTRAS

Aleksej Sidorov



Dob 17.12.1976
Tel +370 650 91030
E-mail a.sidorov@gridins.com

Education / Qualification

1989	Master's degree in transport engineering. Klaipeda University.

Certificate

Magnetic Particle Testing (MT) Level 3;
Penetrant Testing (PT) Level 3;
Visual testing (VT) Level 3;
Ultrasonic Testing (UT) Level 3;
Eddy Current Testing (ET) Level 2;
Driving license - B.
VCA.
IRATA Level 1.
Laboratory Quality System ISO EN 17025 LST: 2005.
Compressed Air Emergency Breathing System (CA-EBS).
Basic Offshore Safety Introduction and Emergency Response Training (BOSIET).

Work Experience

07.2004 – till now	JSC Klaipedos NK centras **Technical director. Head of NDT Laboratory** Responsible for all the technical and technological activities of the company, including: recruitment, ND training and development of personnel, purchasing of equipment and working materials. Testing and approval of reports. Participates in the development and preparation of the ND inspections of various levels of difficulty.
07.1999 - 07.2004	UAB „Vakarų centrine laboratorija" **EN 473 level II NDT Specialist.** Non-destructive testing at various sites in Lithuania and abroad (India, China, Vietnam, Brazil, Norway, the Netherlands).
	Projects:
2003.04 - 2003.05	**Butinges Nafta** - inspection of a communication tower, evaluation of inspection results, preparation of recommendations on maintenance.
2004.06 - 2004.09	**Floating dock AB "Laivite"** – construction's technical condition assessment.
2004.09 - 2004.10	**Klaipedos Vanduo** – assessment of the technical conditions as well as the communication tower's upright positions; Preparation of the report and the specifics of the maintenance.
2005.06 - 2005-07	**Mazeikiu Nafta** – pipeline inspection, evaluation of their condition, preparation for repairs.
2005-06 - 2005.08	**Klaipedos Mediena** – inspection of fire systems and boilers. Preparation of repair specifications.
2006.03 - 2006.05	**Klaipedos Kartonas** – corrosion assessment in pipelines as well as coating condition.
2007.09 - 2007.10	**Philip Morris Lietuva** – pipe and funnel inspections. Preparation of repair specifications.
2007.10 - 2007.11	**AB "Mars"** – pipeline inspection, preparation of reports as well as recommendations on maintenance.
2008.03 - 2008.04	Inspection of the shipboard's crane structure and its bottom hold after a damage. Report drafting for the insurance company.
2008.11 - 2008.12	**Lornac Power Station** – Assessment of the coating.
2009.03 - 2009.05	**Moni Power Station** - inspection of the construction and the surface of the funnel. Preparation of repair specifications.
2009.09 - 2010.03	**Ruways Refinery Jetty, UAE**. Pipeline and steel structure statusing. Preparation of repair specifications.
2011.08 - 2011.09	**"Aker Solutions"** NDT performance on weld joints of cable reels.
2012.04 - 2012.05	**"Sloman Neptun"** - NDT performance on cargo tanks, "Deltagas" vessels.
2014.11 - 2014.12	**"Atlantic Marine Service"** Rig Atlantic Labrador. Performing NDT according to the intermediate survey program.
2014.01 - 2015.01	**JSC "Advantec Lietuva"** NDT performance on weld joints on various steel structures.
2013 - 2015	**JSC "Latvijas Tilti".** Overall project management.
2015	**AB "Lietuvos geležinkeliai".** Overall project management of funnel inspections, reporting.
2015 – 2016	**Wikinger Offshore Wind Farm.** Development, preparation and specialists selection for the project.