KLAIPĖDOS NK CENTRAS


Location:
Hirtshals, Esbjerg (Denmark)
Year: 2016.04-2016.06

Scope of work:

1. NDT (ET, VT and MT) of rig structure according DNV-GL and Customer Periodical Survey Program.
2. UT measurements of rig structure according Periodical Survey Program.
3. Replacement of broken jetting pipes and deep well pumps. Positioning of jetting lines and replacement of pipe supports.
4. Checking leg lamps, changing light bulbs on the legs and crane booms.
5. Dropped objects survey and removal.
6. Washing of legs by using high-pressure machine prior to the inspection and painting.
7. Scaffold erecting and dismantling for repairing crane boom.
8. Damage inspection of cranes, small defect repair and greasing of movable parts. NDT of replaced crane boom bracings.








Project: **Jack Up Intermediate Survey, Jack Up - Special Survey & Jack Up - Annual Survey**























Project: **Jack Up Intermediate Survey,**
Jack Up - Special Survey & Jack Up - Annual Survey

NKC
KLAIPĖDOS NK CENTRAS










Project: **Jack Up Intermediate Survey,**
Jack Up - Special Survey & Jack Up - Annual Survey


KLAIPĖDOS NK CENTRAS
















Project: **Jack Up Intermediate Survey,**
Jack Up - Special Survey & Jack Up - Annual Survey

KLAIPĖDOS NK CENTRAS

KLAIPĖDOS NK CENTRAS

CERTIFICATES:

DNV·GL

APPROVAL OF SERVICE SUPPLIERS

Certificate No:
AOSS0000DTS
Revision No:
1

This is to certify that

UAB Klaipėdos NK Centras

Klaipėdos m. sav., Lithuania

is granted acceptance for
Non-Destructive Testing (NDT) on classification projects , in accordance with Class Programme DNVGL-CP-0484.

This service supplier certificate will be accepted for use with all rule sets published by DNV GL.
See the following page(s) for details regarding application.

This Certificate is valid until **2020-09-01**.

Issued at **Klaipeda** on **2017-11-22**

for **DNV GL**

This document has been digitally signed and
will therefore not have handwritten signatures
Uldukis, Andrius
Station Manager

This Certificate may be withdrawn if:
1. The service provided has been improperly carried out or the results improperly reported.
2. The surveyor has found any deficiencies in the accepted operating systems of the service supplier.
3. The firm has failed to inform of any major changes having effect on the quality of the service rendered.
4. The conditions listed in the certificate are changed and/or are not fulfilled.

© DNV GL 2014. DNV GL and the Horizon Graphic are trademarks of DNV GL AS.

REPUBLIC OF LITHUANIA
NATIONAL ACCREDITATION BUREAU
UNDER THE MINISTRY OF ECONOMY

Lithuanian National Accreditation Bureau is a signatory of the Multilateral Agreements of the European co-operation for Accreditation (EA) for calibration, testing, inspection, certification of products, persons and management systems

ACCREDITATION CERTIFICATE

No. **LA.01.090** Valid until 21/07/2018

The National Accreditation Bureau hereby certifies that the

Testing Laboratory of Joint-Stock Company Klaipėdos NK Centras

Taikos pr. 24a/314. LT – 91222 Klaipėda

complies with the requirements of LST EN ISO/IEC 17025:2005

and is accredited to carry out the tests of

ultrasonic thickness measurements of metallic and non-metallic materials; visual, ultrasonic, penetrant, magnetic particles and eddy current testing of welding seams, welded joints; ultrasonic testing of industrial products where ultrasound can be transmitted

The scope of accreditation is listed in the annex

The first Accreditation Certificate was issued 2008-07-22

Director **Jurgis Šarmavičius**

15/10/2014, Vilnius